Thermometer

Thermometers are used to measure temperature of samples, instruments etc. in a wide range of activities such as manufacturing, testing , research and medical practices, etc
Digital and electronic thermometers are the quickest and most accurate way to measure temperature.

Digital Temperature Indicator:

Imported Make



Battery operated with 12" long probe and one meter wire with temperature sensor.
Range : - 50 to 1300°C

Temperature sensors are available in two types.
- Rod type
- Bead type

Ordering Informations:

Ref No. 601 Thermometer
HSN Code: 90258090