Hiding Chart

Opacity Charts

Opacity charts are used to analyse the hiding power (Opacity) of the prepared paint and coatings. We provide two types of opacity charts which are given below in the table.

Chart No./ Ref No.	Category	Size	Chart Type
201 - B	Black on Bottom	6” x 4”	Glossy
301 - B	Black on Bottom	6” x 4”	Matt
201 - D	Black on Top	10” x 6”	Glossy
301 - D	Black on Top	10” x 6”	Matt



