RAJ®

Hiding Chart

Plain White Charts

Plain white charts are used to produce true colour samples without any interference of black substrate. We provide plain white charts in three types which are given below in the table .

Chart No./ Ref No.	Size	Chart Type
210	10” x 6”	Glossy
211	10” x 4”	Glossy
310	10” x 6”	Matt



