

### Thermo Hygrometer

Thermo hygrometer is used to measure the temperature and humidity of the environment. It has a dual digital LCD display each showing humidity and temperature. It consists of two keys with the help of which we can set temperature and humidity with the help of MAX/MIN and RESET is used to attain an already set temperature and humidity. Timer and alarm facility is also provided in the instrument. Wall hanging and table top facility is also given.

Temperature Range : - 10 to 50°C

Humidity Range : 25 - 95 % RH

#### Ordering Informations:

Ref No. 720/1 Thermo Hygrometer - Normal display

Ref No. 720/2 Thermo Hygrometer - Jumbo display

**HSN Code:** 90258090

